## **BSI-Inspectorate America** 178 Mortland Road Searsport, Maine 04974





## **QUALITY CERTIFICATE**



SHORE TANK NO. 4 Vessel Customer **SPRAGUE ANALYSIS** Operation

Port Date

Terminal

SEARSPORT, MAINE October 3, 2005 **SPRAGUE** 

Report SP/05/1002 Reference V-05-01436 Sample # 326987

Name of material being tested Description of sample source Samples Drawn by (company) Samples Tested by (company)

## **NO. 6 FUEL OIL 2.0%**

EX. SHORE TK NO. 4 AFTER DISCHARGE OF NORMAN MCLEOD **BSI-INSPECTORATE BSI-INSPECTORATE** 

Tests being Performed	Test method	Minimum Maximum	Sample Source
MW-1			
GRAVITY, API @ 60 F FLASH POINT, F VISCOSITY, SSF @ 122 F POUR POINT, F WATER & SEDIMENT, % VOL.	ASTM D 4052 ASTM D 93 ASTM D 445/2161 ASTM D 97 ASTM D 1796		11.4 200+ 244 +32.0 0.01
SULPHUR, % WT. )H, % WT.  VANADIUM, PPM SODIUM, PPM BTU'S/POUND	ASTM D 4294 ASTM D 482 AA/AE AA/AE CALCULATION		1.48 0.02 67 16 18,392
BTU'S/GALLON NITROGEN, % WT. CARBON RESIDUE, % WT. ASPHALTENES, % WT.	CONVERSION ASTM D 5762 ASTM D 4530 IP-143		151,679 0.3733 9.43 2.52
SPRAGUE PROVIDES THE ATTACHED INSPECTION REPORT/ANALYSIS REPRESENTING THE SPECIFICATIONS OF THE PRODUCT AT THE SPRAGUE TERMINAL IN TANK ON THE DATE OF INSPECTION NOTED ON THE CERTIFICATE. THIS ANALYSIS IS PROVIDED TO THE CUSTOMER FOR THE PURPOSE OF ESTABLISHING THE INDEPENDENTLY VERIFIED PRODUCT SPECIFICATION ON A COMPOSITE BASIS IN SPRAGUE'S TERMINAL SHORE TANK AS NOTED ON THE CERTIFICATE. THE INSPECTION REPORT IS NOT TO BE USED FOR ANY OTHER PURPOSE. SPRAGUE DISCLAIMS ANY LIABILITY FOR THE PRODUCT AFTER DELIVERY BY SPRAGUE TO CUSTOMER. SPRAGUE DISCLAIMS ANY WARRANTY OF MERCHANTABILITY OR FITNESS FOR AN INTENDED USE EXCEPT AS MAY BE SPECIFICALLY SET FORTH IN WRITING IN ANY CONTRACT OR TERMS OF SALE BETWEEN SPRAGUE AND A BUYER OF PRODUCT. SPRAGUE ASSUMES NO LIABILITY FOR CLAIMS OR LOSSES THAT MAY ARISE FROM CUSTOMER'S USE OF THIS INSPECTION REPORT/ANALYSIS.			
AND A BUYER OF PRODUCT. SPHAGUE ASSUMES THAT MAY ARISE FROM CUSTOMER'S USE OF	5 NO LIABILITY FOR CLAMS OR LUSSES THIS INSPECTION REPORT/ANALYSIS.		